

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3241

Date Inspected June 8

I so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth


Size of pipe used 4 in

Was lateral at curb? yes

Name of Contractor

Was attached to main _____

Show by diagram relation of lateral to wall of building served.



Signed A. F. Boyd

Inspector for City

0 Main Sewer North
9th St. N. E.

Filed at Engineer's Office

JUN 14 19

Remarks:

Lateral connected to lateral at curb 8 ft from M
Hole

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3241

PERMIT TO TAP SEWER

Massillon, O., 6-7-19

Received of Mrs. Fred. Snyder fee of \$ 2.00

for which permission is granted Jesse Brumaker

to tap Sanitary sewer, on the East

of 9th St. N.E. Ave., Type of Street Dist.
St.,

the premises being Lot No. 286 (968) House No. New

Work to be done in accordance with Ordinance No. 2929, duly passed by the City Council, and Ru
the Department of Public Service.

Name of Contractor Jesse Brumaker

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.