

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3248

Date Inspected _____ I so how and location from
first manhole down stream _____

House No. 663 _____ Distance from first manhole
down stream to ditch at _____

Size of pipe used _____ curb line and depth _____

Was lateral at curb? _____

Name of Contractor _____

Was attached to main _____

Show by diagram relation of lateral to wall of building served.

House

Main Sewer

Highland ave

JUL 5 1921

Signed _____

Inspector for City

Filed at Engineer's Office

Remarks: _____

No Inspection

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 3248

PERMIT TO TAP SEWER

Massillon, O.,

6-15

19

Received of

H. A. Bowers

fee of \$

2⁰⁰

for which permission is granted

Sam Franklin

to tap

Secretary

sewer, on the

Franklin

of

Regiment

Ave., Type of Street

St.,

Franklin

the premises being Lot No.

OK 83

House No.

663

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.

Name of Contractor

Sam Franklin

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.