

✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3291

5-19

Date Inspected July 16th I so how and location from
House No. New 941 first manhole down stream.
Size of pipe used 6 in Distance from first manhole
down stream to ditch at
curb line and depth.
Was lateral at curb? yes
Was attached to main
Name of Contractor Geo Brunner
Show by diagram relation of lateral to wall of building served.

House

6
28 ft pipe

7 1/2

Man Hole → Main Sewer South ←
Biner P. L. N. E.

Signed A. F. Boyd
Inspector for City

Filed at Engineer's Office

JUL 29 1929

Remarks: Lateral connected to lateral at curb 125 ft from Ma
1 Bend at curb Hole

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 3291

PERMIT TO TAP SEWER

Massillon, O., July 15 1917

Received of Jesse Brunner fee of \$ 2.00

for which permission is granted C. Brunner

to tap 8 sewer, on the W view of locality

of Brunner Pl. N. E. Ave., Type of Street Art
St.,

the premises being Lot No. 7855 4124 (old), House No. 941

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.

Name of Contractor Jesse Brunner

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.