

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3296

Date Inspected July 20

I so how and location from
first manhole down stream.

House No. 218

Distance from first manhole
down stream to ditch at
curb line and depth.

Size of pipe used 6 in


Was lateral at curb? yes

Name of Contractor

Geo Brunner

Was attached to main

Show by diagram relation of lateral to wall of building served.



5 1/2 38 ft pipe

Main Sewer South →
11 th St N. E

Signed

A. F. Boyd

Inspector for City

Filed at Engineer's Office

Remarks

lateral connected to lateral at curb 2 ft from Strai
line on House

JUL 23 1929

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3296

PERMIT TO TAP SEWER

Massillon, O.,

19

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

of

Ave., Type of Street
St.,

the premises being Lot No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.