FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected July 95 House No. 448	I so how and location from first manhole down stream
House No. 448 Size of pipe used £ 2012	Distance from first manhole down stream to ditch at the best such curb line and depth
Was lateral at curb?	Name of Contractor Dame Franklin
Show by diagram relation of lateral	
Names Nor	ovitairanieces 45; 45 pipe
A bun figure) 700 (10) who fi become visit	· //
. A of Russ	Main Dewer Wieth 27 th Al-W. W. Filed at Engineer's Office JUL 79
Signed A Day A Inspector Remarks: Lateral Com	

 $\sim N_{\odot}^{0}$ 3306

a to be anavered by inspector

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N_0 3306

PERMIT TO TAP SEWER

aidiā soitess areside av elockary seek	Colodonio 1	Massillon, O.,	fee of	- -
Received of			ra hannarin le	\$_ <i>E</i> _= -]/
or which permission is granted.	Dagra C	D Z 1541	inenzilli T	1407
o tap Marietany	sewer, o	on the	100%	35.01
of 27 7	#)//// AT	ve., Type of Street	Al-	<i>1</i>
the premises being Lot No.	りつにん	st., , House No.	49	19

the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of buils subject to Massillon Board of Health Regulations.