FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

Nº 3318	AND SIGNED WHEN RETURNED
Date Inspected flesh 3/ House No. 5/10 Size of pipe used 6 22	I so how and location from first manhole down stream Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb?	Name of Contractor & Whithman
Show by diagram relation of laters	이 보다는 하다는 경우는 이 생각에 가장하고 본자를 가지는 때문에서 있다. [^ # 12 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
ile salville. nin Alamad vilvesik ve besesh vin	
Signed A. A. Band	Mann Server Worth € 23. Mann Server Worth € 93. Mann Server Worth € 10. Filed at Engineer's Office. JUL 3.1.19
Remarks: Sateral com	Filed at Engineer's Office. JUL 3110 rected to ald lane 4 ft from Shait line on

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3318

PERMIT TO TAP SEWER

	inosi vetisiolik messia nyis i sinolla Liisa	ranneiseach bas wad as i serly arge eledaser sera Massillon, O., (MA) 21 rannei (Special)		
Received of	//		M 14	
for which permission is	granted	1986. Geografi	11 addin-D	~~
to tap	<u>an de </u>	sewer, (on the	a ni jebio A riol Datarran va wor i
of <u>:?3</u> 72	1 -24/		e., Type of Street	ded
he premises being Lot	No. 18 =	7347	st., House No.	5/0
Work to be done in ac	cordance with (Ordinance No. 2	323, duly passed by t	the City Council, and
he Department of Pu	blic Service.			
Name of Contractor	سدور والمداري	Witten	ann	

NOTE. This permit covers work outside of building only. Any work inside walls of buils subject to Massillon Board of Health Regulations.