FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3329

Date Inspected Aug 12

House No. 3133

Size of pipe used 6 in

Was lateral at curb? yes

Was attached to main

Show by diagram relation of lateral to wall of building served.

I so how and location from first manhole down stream

Distance from first manhole down stream to ditch at curb line and depth

Name of Contractor Sam Franklin



Signed A T Boyd
Inspector for City

Lincoln Way W. W.
Filed at Engineer's Office AUG 15 19

Remarks: Lateral connected to lateral at main 4 ft from Str
line on Hou

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3329

PERMIT TO TAP SEWER

Massillon, O., Jan 9 12nd 19

Received of [illegible] fee of $ 2

for which permission is granted [illegible]

to tap [illegible] sewer, on the [illegible]

of [illegible] Ave., Type of Street [illegible]
St.,

the premises being Lot No. 7512, House No. 3123

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.

Name of Contractor [illegible]

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.