FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Ach 3	I so how and location from first manhole down stream
House No. 1540	Distance from first manhole down stream to ditch at
Size of pipe used 6.444	curb line and depth
Was lateral at curb 2018	Name of Contractor Jam Augslan
Was attached to main	
Show by diagram relation of lateral	
	199 15 All
i him Kimun) qua od vi kessu vich .	300 是2016 中国的企业的企业的企业的企业的企业的企业的企业的企业的企业的企业的企业的企业的企业的
	The Department of Public Survey
Signed A. T. Bruse	Dyran aff as . W Affled at Engineer's Office SED 0
Signed V Inspector	
Inspétor Remarks: Salval Canni	ested to lateral at euro 20 ft from strai
	line on House

Nº 3351

OTSITERI YE GESTEWRED BY DY AT

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 \mathbf{N}^{o} 3351

PERMIT TO TAP SEWER

i se imperator ingator income ingatoria sidula sidula alcenga	Massillon, O.,
Received of 7	fee of \$
for which permission is granted	
to tap i sewe	r, on the
of Sulfamental Sul	Ave., Type of Street
the premises being Lot No.	
Work to be done in accordance with Ordinance No.	. 2323, duly passed by the City Council, and ${ m R}$
the Department of Public Service.	
Name of Contractor	LLY TO D