FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Aug 30	I so how and location from first manhole down stream	
House No. \$ 79	Distance from first manhole down stream to ditch at	
Size of pipe used 6 224	eurb line and depth	
Was lateral at curb?	Name of Contractor Le Carlos Markey	
Show by diagram relation of lateral to	wall of building served. House	
and the state of t	8-4-> []	
	Fram 1/3-	
22, doly passed by the City Cornell, and Ki	CE Lot be deserve acceled by Styles with the W	
	Main dever East <-	
Signed A A Bryd	Bielhern and S. E. AUG 31) 1 ¢
Inspector for Remarks: Aalt al Count		IJ
	lind on Ha	U

Nº 3355

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

for which permission is granted ve., Type of Street __, House No. the premises being Lot No. Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru

MIT TO TAP SEW

NOTE. This permit covers work outside of building only. Any work inside walls of bu

is subject to Massillon Board of Health Regulations.

the Department of Public Service.