

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 3386

Date Inspected Oct-4

I so how and location from
first manhole down stream

House No. 1814

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in


Was lateral at curb? yes

Name of Contractor

Jes Brunner

Was attached to main

Show by diagram relation of lateral to wall of building served.



Signed A T Boyd Man Hole 0 Main Sewer North
Inspector for City Eric St South
Filed at Engineer's Office

OCT 15 192

Remarks: lateral connected to lateral at curb 15 1/4 from Ma
Hole

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3386

PERMIT TO TAP SEWER

Massillon, O., Oct 1st, 1918

Received of James Brunker fee of \$ 2.00

for which permission is granted Frank F. Shuman

to tap Sanitary sewer, on the East

of East 1st Ave., Type of Street paid on
St.,

the premises being Lot No. _____, House No. 1814 1/2

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor James Brunker

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.