

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No 3415

Date Inspected Nov 4

I so how and location from
first manhole down stream

House No. 934

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used

Was lateral at curb?

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

Signed

Inspector for City

Filed at Engineer's Office

NOV 12 1929

Remarks:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3415

PERMIT TO TAP SEWER

Massillon, O., Mar. 5 1920

Received of Wm. Anderson fee of \$ 2.00

for which permission is granted _____

to tap sanitary sewer, on the East

of 14th St. S. E. Ave., Type of Street dirt
St.,

the premises being Lot No. Pl 1921, House No. 934

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor Not known

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.