FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED N? = 3428Date Inspected Note-27 I so how and location from first manhole down stream. House No. 15.30

Distance from first manhole down stream to ditch at Size of pipe used 6. A.

Was lateral at curb?🕢 🚉 .

Was attached to main...

Show by diagram relation of lateral to wall of building served.

curb line and depth.

Mosauce No. 2022. Out possed by the City Council, and think

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3428 PERMIT TO TAP SEWER

in the state of the	ie i schi tete wod cz s oweb, elokasarde	Massillon, O.,.	200	35 5 19 19
Received of	我们的 医内侧性皮肤 医多种性 医多种畸形		The factor of the state of the state of the	Saver Ade ("Bahi") paris Met il francia di di
for which permission is gran				e Charles Tage
to tap		이 동일하다는 사람들은 아무슨 사용을 걸었다.	열면 대학교의 사고기를 받는다.	Acadis 4677
of / J	t Tre	Ave., Type of a	Street	Brick
the premises being Lot No	10161	, House	No	
Work to be done in accordan	ce with Ordinance 1	No. 2323, duly pass	sed by the Cit	y Council, and R
the Department of Public Se		A PARTICULAR (A)		
Name of Contractor		<u> </u>		
NOTE This borns	it coners morb outsi	do of heilding only	Ann mark	inside malls of h

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.