FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED Date Inspected. I so how and location from first manhole down stream. House No. _ Distance from first manhole down stream to ditch at Size of pipe used. curb line and depth. Was lateral at curb?. Name of Contractor. Was attached to mai Show by diagram relation of lateral to wall of building served. Signed. Inspector for City Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 \mathbf{N}^{o} 3443

PERMIT TO TAP SEWER

rodur neitemikties visik es diesats dispositionel	Massillon, O. 19
Received of Santa Received	(5000000000000000000000000000000000000
for which permission is granted.	A Branky
	wer, on the
of <u>219 43 Nuc.</u>	Ave., Type of Street St.,
the premises being Lot No. 7544	, House No
Work to be done in accordance with Ordinance I	No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.	

NOTE. This permit covers work outside of building only. Any work inside walls of builts subject to Massillon Board of Health Regulations.