FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

1 Nº 3466	AND SIGNED WHEN RETURNED
Date Inspected	I so how and location from
House No.	Distance from first manhole  down stream to ditch at
Size of pipe used.	curb line and depth
Was lateral at curb?	Name of Contractor ANN MUNRUL
Was attached to main $I$ $U$ Show by diagram relation of late	eral to wall of building served.
	οΤ , ενήλ St., Σ
Total No.	
7MH0 148	Fork to be done in ser vience whit Ordinance No. <b>5</b> 23, du
) all	The Department of Ending Sections 1
Signled Frank	Filed at Engineer's Office 4/14/30
Inspection of the contract of	ctor for City windows Santage
Remarks:	Le Company

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER for which permission is grante Ave., Type of Street. Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service. Name of Contracto This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.