

South

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 3468

Date Inspected 4/14/30 I so how and location from
2417 first manhole down stream

House No. _____ Distance from first manhole
Size of pipe used 6" down stream to ditch at
curb line and depth _____


Was lateral at curb? No

Was attached to main Yes

Name of Contractor

Sam Franklin

Show by diagram relation of lateral to wall of building served.



APR 15 1930

Signed Frank B. Jones
Inspector for City

Filed at Engineer's Office

Remarks: _____

North

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3468

PERMIT TO TAP SEWER

Massillon, O.,

April 10 19

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

of

Ave., Type of Street
St.,

the premises being Lot No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 10 of the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.