FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected <u>ゴーセ3ー 3</u>	O I so how and location from i first manhole down stream	
House No, 2//	Distance from first manhole	de Tslañ
Was lateral at curb? <u>y Es</u> Was attached to main <u>y Es</u>	Name of Contractor 2 4 C 1 - C 4	lein.
Show by diagram relation of later	al to wall of building served.	
A∵re⊸ odcagueH.	z' 2 3 3 3 4 4 4 4 4 4 4	
	1888 7. F. f. a. f. Car. 6. 38: - 16: 1888	

Inspector for City

Remarks: Used 6 x 6 vive at cellar deain, then continued west to tap 4

Pipe to Septic tann, plugged inlet to septic tann,

NE ANSWERED BY INSPECTOR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 N_{\parallel}° 3478

PERMIT TO TAP SEWER

	ii noriidai badiyadi Aileliyob eledad	100000	ssillon, O.,	こうしょう シェ ぎょりんさい さいじ	per file of the company of the com-	to the angles of the same and and
Received of	Sand-		En	e Ø	fee of	\$.25
for which permission is g	ranted		Form	م محرب بدران الم		De floren
to tap	Lary	sewer, on	the	We	。我	
ot 260	EXR	A Kave	, Type of S			-1-1
the premises being Lot No		, St.,	, House			
Work to be done in accor	The first of the control of the cont	nce No. 232	B, duly passe	ed by the (City Counci	il, and Ru
the Department of Publi	s Service.					
Name of Contractor	Jan F	Fand	90			

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.