

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No 3495

Date Inspected 5.8.30

House No. 472

Size of pipe used 6" V.S.P.

Was lateral at curb? Yes

Was attached to main _____



Show by diagram relation of lateral to wall of building served.

I so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth

Name of Contractor

Sam Franklin



Signed _____

Geo. C. Wallace
Inspector for City

Filed at Engineer's Office

MAY 8 1930

Remarks: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 3495

PERMIT TO TAP SEWER

Massillon, O.,

5.8

19

Received of

Sam Franklin

fee of \$

2.00

for which permission is granted

Sam Franklin

to tap

Sanitary

sewer, on the

East

of

27th St SW

Ave., Type of Street

Driv

St.,

the premises being Lot No.

4380

, House No.

472

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Run the Department of Public Service.

Name of Contractor

Sam Franklin

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.