FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

line on Hous

Date Inspected Pune 23	I so how and location from first manhole down stream
House No. Size of pipe used A 222	Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb?	being a si nor pores north ros
Was attached to main	Name of Contractor Ald Bounkley
Show by diagram relation of lateral	l to wall of building served. House
	as a just yoff fife
e ilinuotyji(Ledi 10 desesa viub	1988 of engratural or interpression 174 to at it state.

e to be abswered by inspector Caro electroceto

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 N° 3617

PERMIT TO TAP SEWER

The second secon	sef fine well on it.	ρ	baloogenl, afau
Received of	ob slovinces terd N in mon opposett i et esprendische	Massillon, O.,	fee of \$2
for which permission is granted	inis bushkulistano	Brunds	sau ogių io ėzis
to tap	sewer; c	of relation of lateral to	1. Acostrá sevi encelo pel profis
of 27	Av SE Av	e., Type of Sireet	did
the premises being Lot No	198	, House No. 🖊 😤	6
Work to be done in accordance w	ith Ordinance No. 28	323, duly passed by the	City Council, and R
the Department of Public Service		1	
Name of Contractor			
		ioi-tordenal de la	

NOTE. This permit covers work outside of building only. Any work inside walls of buils subject to Massillon Board of Health Regulations.