## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N?==3683

Date Inspected APTI 14,1	7.24. I so how and location from first manhole down stream
House No. 2505	Distance from first manhole
Size of pipe used	down stream to ditch at 42 ft 6 deep.
Was lateral at curb?	Name of Contractor Geo Early
Was attached to main	Name of Contractor C/PO [_A/]
Show by diagram relation of latera	to wall of building served Phode Island Ave S
<b>☆</b>	42° Approx. curb
	6º Deep
TZW	Existing Septic 19 Pipe -1-6x4 Reducer a:
the Second will call to be seen to be	Approx, Location
مراوان	Approx, 200011000 -12° -12°
	Parch 1
Signed Sylvanor K	House APR 1 6 1934
	Filed at Engineer's Office

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 $N_0$  3683

## PERMIT TO TAP SEWER

Received of for which permission is granted sewer, on the ..., House No. the premises being Lot No. -Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service. Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of bu

is subject to Massillon Board of Health Regulations.

16