

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 3708

Date Inspected March 8-35

I so how and location from
first manhole down stream

House No. 1455

Distance from first manhole
down stream to ditch at

Size of pipe used 6"

curb line and depth 224' 6" FROM M.H. at NISH. 8.5 D.

Was lateral at curb? YES


Name of Contractor GEO. EARLY

Was attached to main

Show by diagram relation of lateral to wall of building served.

*insp. called out at
10:36 A.M. got their on time*

*NISH
Avenue*



W. Curb. 8.5 Deep

MH 224.5 -> Main sewer

Signed [Signature]
Inspector for City

Filed at Engineer's Office. MAR 13 1935

Remarks: BEND and one joint. Pipe connected and back filled before
got on job.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3708

PERMIT TO TAP SEWER

Massillon, O., March 5, 1919

Received of John C. Lamb fee of \$ 2.00

for which permission is granted John C. Lamb

to tap Sanitary sewer, on the West

of 1st St. Ave., Type of Street Public
St.,

the premises being Lot No. 2743, House No. 1455

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor John C. Lamb

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.