FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

No. 3721

Date Inspected Cor 30/14

House No. 617

Size of pipe used 6"

Was lateral at curb? Yes

Was attached to main Yes

Show by diagram relation of lateral to wall of building served.

1 so how and location from first manhole down stream

Distance from first manhole down stream to ditch at curb line and depth 4FT. 6" FROM M.H.

Name of Contractor GEO. EARLY



Signed Samuel Jones
Inspector for City

Filed at Engineer's Office MAY 20 1935

Remarks:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3721

PERMIT TO TAP SEWER

Massillon, O., [illegible] 30 19

Received of [illegible] fee of $2.

for which permission is granted [illegible]

to tap [illegible] sewer, on the [illegible]

of [illegible] Ave., Type of Street [illegible]
St.,

the premises being Lot No. 01 1853, House No. 617

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru

the Department of Public Service.

Name of Contractor [illegible]

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.