FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED - 3755 Date Inspected so how and location from first manhole down stream. House No. -Distance from first manhole down stream to ditch at Size of pipe used. curb line and depth_____ Was lateral at curb? Name of Contractor Was attached to main Show by diagram relation of lateral to wall of building served.

N° 3755

PERMIT TO TAP SEWER

	o key naidadhin Trom Cusanda Sova gugan L	Massillon, O.,	1. 1.5 1.
Received of	化电子工作 化二十二烷基甲基二烷 医二烷 化二氯磺胺二甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基	allaneest	fee of \$_2.0
for which permission	is granted	1/2/21	induscia in asia. Tanàna
to tap	12.1-1	ewer, on the	south
of Coant	Le cul land	Ave., Type of Street	ant.
	77.1	St., House No.	경기 등 기가를 가득 기가 있다며 불살을 살았다.
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru			
the Department of I			
Name of Contractor	I) I Ama-	<u> L</u>	

NOTE. This permit covers work outside of building only. Any work inside walls of bit is subject to Massillon Board of Health Regulations.

18