

Wen

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3770

Date Inspected *11/25/25* I so how and location from first manhole down stream *85' 0"*

House No. *1125* Distance from first manhole down stream to ditch at


Size of pipe used *6"* curb line and depth

Was lateral at curb? *Yes under side walk*

Was attached to main *Yes* Name of Contractor *Smart*

Show by diagram relation of lateral to wall of building served.

*One foot north of South West corner of house is lateral connection
Side walk 11 ft.
8' 0" Deep at curb
Fast. S. H. F.*



Signed *Frank B. Jones*
Inspector for City

Filed at Engineer's Office

Remarks

*Enters basement north West corner of house?
East*

NOV 26 1925

1st - having & loan wanted the connection in the rear, instead of coming out in front of house, as usual, to the street

9-11-10
7-9-10
4/10
F. Jones
Elevation not correct

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3770

PERMIT TO TAP SEWER

Massillon, O., June 25 1917

Received of L. W. Luman fee of \$ 2.00

for which permission is granted Frank Luman to

to tap Sanitary sewer, on the west

of 1st N. W. E. Ave., Type of Street residential
St.,

the premises being Lot No. 2688, House No. 1125

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor L. W. Luman

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.