

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No 3777

No.

Date Inspected 3-13-36

I so how and location from
first manhole down stream

House No. 226

Distance from first manhole
down stream to ditch at

Size of pipe used 4"

curb line and depth Lat at CURB. 19 12' SO. OF SO. CURB OF
THORN and 15 5' DEEP.


Was lateral at curb? YES

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

*Serviciced joints used with cement
Ran rods thru to main line before
connection was made; line was O.K.*



Signed Sheffer

Inspector for City

Filed at Engineer's Office

Remarks: Lat at CURB. 19 23' North of South side of house

MAR 14 1936

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 3777

PERMIT TO TAP SEWER

Massillon, O.,

Received of

fee of \$ 2.00

for which permission is granted

to tap

sewer, on the

of

Ave., Type of Street
St.,

the premises being Lot No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.