

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3789

Date Inspected May 16, 1936

House No. 724

Size of pipe used 6" Prestite

Was lateral at curb? yes

Was attached to main no

Show by diagram relation of lateral to wall of building served.


4" to cellar drain
Depth 7'

I so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth

Name of Contractor

Geo. Early



Signed

Filed at Engineer's Office

Inspector for City

Remarks:

19' from back of house to clean out, 3 feet from house

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3789

PERMIT TO TAP SEWER

Massillon, O.,

Received of

fee of \$2.00

for which permission is granted

to tap

sewer, on the

of

Ave., Type of Street

St.,

the premises being Lot No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.