

✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED


No. 3801

Date Inspected 6-17-36 I so how and location from
first manhole down stream.....
House No. 658 Distance from first manhole
down stream to ditch at
Size of pipe used 6" curb line and depth 223' From 174. at warwick 6" Deep
Was lateral at curb? YES

Was attached to main..... Name of Contractor GEO. EARLY

Show by diagram relation of lateral to wall of building served.

T-K. and CALK TITE used
for joints with gute filler.



Signed Shertzer Inspector for City Filed at Engineer's Office JUN 17 '36

Remarks: Lateral CURB line is 11 ft. so. of south side of house and enters
basement 2' East of front of house

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3801

PERMIT TO TAP SEWER

Massillon, O., June 13 1926

Received of D. C. Falkman fee of \$ 2.00

for which permission is granted Alex. Early

to tap sanitary sewer, on the west side

of Lot 11 Ave., Type of Street dead St.,

the premises being Lot No. 3564, House No. 658

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rules of the Department of Public Service.

Name of Contractor Alex. Early

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

1-15-37
222
6461
1251
5/10