

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 3809

Date Inspected 6-30-36

I so how and location from first manhole down stream OR measurement from

House No. 665

Distance from first manhole sewer Record
down stream to ditch at
curb line and depth

Size of pipe used 6"


Was lateral at curb? yes - 2 ft

Name of Contractor Geo. Early

Was attached to main

Show by diagram relation of lateral to wall of building served.

GROOSE AVENUE



Signed

Inspector for City

Filed at Engineer's Office

Remarks:

Lateral was found 2 ft. from curb. Used 1 pipe the 1/2 Bend.
Roots were found in sewer when plug was removed

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 3809

PERMIT TO TAP SEWER

Massillon, O., June 29 1911

Received of

fee of \$2.00

for which permission is granted

to tap

sewer, on the

of

Ave., Type of Street

St.,

the premises being Lot No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

1-13-11
5/10