

North

✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3830

Date Inspected Sept 9/1936 I so how and location from
first manhole down stream


House No. 3006 Distance from first manhole
down stream to ditch at
Size of pipe used 6" curb line and depth

Was lateral at curb? yes

Was attached to main yes

Name of Contractor Smart

Show by diagram relation of lateral to wall of building served.



Signed

Inspector for City

Filed at Engineer's Office

Remarks:

17' 0" of pipe

9/21/36

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3830

PERMIT TO TAP SEWER

Massillon, O., Sept 21 1919

Received of L. H. Smart fee of \$ 2.00

☒ for which permission is granted.

to tap San Sewer sewer, on the north

of Lincoln Way N.W. Ave., Type of Street opening
St.,

the premises being Lot No. 01. 185, House No. 3006

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 10, of the Department of Public Service.

Name of Contractor L. H. Smart

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

7 1/16-37
5