FOLLOWING DATA TO BE AL

 $N_{\cdot}^{0} = 3831$

Date Inspected...

Size of pipe used

Was lateral at curb?

Show by diagram relation of lateral to wall of building served.

Inspector for City

Ave. . Type of Street

Was attached to main

House No.

Remarks:

140717

I so how and location from first manhole down stream.

Distance from first manhole down stream to ditch at

South

curb line and depth...

Filed at Engineer's Office...

VERED BY INSPECTOR

٠,		٠						
٠	Ŀ			۰		-	•	٠
г	٠		٠.					L
ı	3	٠		٠	1	1	Й	b
•		N	٠,	•	•	-13	,	₹

AND SIGNED WHEN RETURNED

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEW for which permission is granted the premises being Lot No

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service.

Name of Contractor / 1 / Land

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.