FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

Nº 3884

AND SIGNED WHEN RETURNED

Date Inspection		and location from		
House No. New Bldg (Ges C	🗩 💢 down stre	am to ditch at	vienski de de de de	
Size of pipe used 6"V.S. Was lateral at curb? Reloy 6		and depth	lobline went	+ thru propos
Was attached to main /e.	Name of (Contractor	Geo, Fo	75/4
Show by diagram relation of later	al to wall of build	ing served.	Brick Bldg	
· New York of the Property of	≠ '9'	1 8º Deep ±	(<u>//////</u> Castinatin tell	6"V,SP
thy passed by the City Council, and		47	40	The second secon
· 1 p &	N G	Frome ac	Propose Blad Office Geo Or	16"15
Signed Inspect	or for City	Filed at Engin	I VOV	Kina; i

ACTOTERM OF CENTROLES OF COLORS OF C

PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

