




**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 3898

Date Inspected 7/10/37 I so how and location from first manhole down stream 18'
House No. New House Distance from first manhole down stream to ditch at curb line and depth 18' 5' 6" deep
Size of pipe used 6
Was lateral at curb? Yes Name of Contractor Geo. Farley
Was attached to main Yes
Show by diagram relation of lateral to wall of building served.



4TH ST, N.E.
M.H.

Signed John E. Hanner

Inspector for City

Filed at Engineer's Office

JUL 13 37

Remarks: Seems like plumber drove soil pipe under wall, when uncovered by Earl
pipe full of dirt. don't know how far back dirt extended
from Clean out inside of wall to vit Pipe was washed out ok

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 3898

PERMIT TO TAP SEWER

Massillon, O.,

7-10

19

Received of

Don Scott

fee of \$ 2⁰⁰

for which permission is granted

Gen Early

to tap

Sanitary

sewer, on the

East

of

4TH ST NE

Ave., Type of Street

Block

St.,

the premises being Lot No.

672

, House No.

new house

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and by the Department of Public Service.

Name of Contractor

Gen Early

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.