	AND SIGNED WHEN RETURNED	FOLLOWING DATA TO BE ANSWERED BY INSPECTOR		
$-\mathbf{N}_{-}^{0}$ 3908		AND SIGNED WILLIA RETURNED		
Date Inspected	I so how and location from			
House No. $\frac{3}{7}$	Distance from first manhole down stream to ditch at			
Size of pipe used	curb line and depth 127 56"			
Was lateral at curb?	Name of Contractor Let Curilly			
Was attached to main $V$	Name of Contractor / Carly			
Show by diagram relation of l	lateral to wall of building served.			
BASE TO				
\ <sup>‡</sup> 317 <sup>)</sup>		0/6 )		
1317		of )		
	Sign and and an enobled of their M.H.	015) \$410)		
	FOR LESS COMMENTED TO STATE OF THE STATE OF	014 8 aw )		
	167-24 C 127 T O	edu)		
	Social State Condense of the Man State o	caw)		

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

91		Massillon, 93,	17
Received of	graden brody some Lagradia Anti-On	2-dy	/
or which permission is grant d	一点性自動學 医生物的 经免款的复数形式	ラー・レス	L. a. de
中央电影 医动物切除术 医多异性病 化多压剂 经多种基础	the first of the continue to the first of the first of the continue to		,
0 tap 16-11/16	1 81	ewer, on the	nomente.
of 1 st 14 %	$\mathcal{U}^{-1}$	Aye., Type of Street	
		St.,	
he premises being Lot No	42	House No.	317

NOTE. This permit covers work outside of building only. Any work inside walls of building only. Any work inside walls of building only.