

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 3945

DATE INSPECTED 12/21/37

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1820

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

125' 6' deep

WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR


Smart

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

HOUSE

LINDBERGH AVE. N.E.



SIGNED

John E. Hinner

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

DEC 22 37

REMARKS:

800
8/31
Ledger Sept 15, 1940

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 3945
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/20 1940
RECEIVED OF L. W. Smart FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Res W. Dubel
TO TAP Sanitary SEWER ON THE north
OF Lindbergh Ave. N.E. AVE., TYPE OF STREET Dist
St.,
THE PREMISES BEING LOT No. 9090, House No. 1820
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR L. W. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.