

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3948

DATE INSPECTED 1/18/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

23'

HOUSE No. 1834

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

23' 6" deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes


NAME OF CONTRACTOR

Smart.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

LINDBURGH AVE. N.E.

Flushed mud out of
LATERAL before laying pipe
To house. 1/17/38 - Piper & Emmer



M.H. 0

CURB LINE.
23 FT

SIGNED

John Emmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

Smart.

REMARKS:

8
31
Sedgwick Oct 1. 1948

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o. 3948
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/8 19
RECEIVED OF Geo. W. Denbke FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED L. H. Lincart

TO TAP Sanitary SEWER ON THE North

OF Landtonght AVE., TYPE OF STREET Gravel
St.,

THE PREMISES BEING LOT No. 909-3 House No. 1834

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. H. Lincart

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.