

NO. 3952

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

NO RECORD

DATE INSPECTED 3/21/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

91' - 7' deep

HOUSE NO. 847

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

93' 5" deep

WAS LATERAL AT CURB? NO

NAME OF CONTRACTOR

Geo Earley

WAS ATTACHED TO MAIN NO

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

STATE AVE. N.E.

9TH ST. N.E.

← N. →

CURB LINE

91'

93'

7' deep

5' deep

HOUSE

End? → No M.C.
8" Main, Cement joints
In good condition
7" Deep in Street.

SIGNED

21

John Ehmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Tapped on main

No 3952

PERMIT TO TAP SEWER

NO RECORD

All opening permit # 3411

MASSILLON, OHIO, 3/19 19

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.