

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 3957

DATE INSPECTED

4/2/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

148'

HOUSE NO.

1216

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

148' - 3' deep

SIZE OF PIPE USED

4

WAS LATERAL AT CURB?

Yes


NAME OF CONTRACTOR

Geo Earley

WAS ATTACHED TO MAIN

Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John E. Brown

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

APR 1 1938

REMARKS:

END OF LATERAL WAS 3' FROM CURB.

3/2

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

No. 3957

MASSILLON, OHIO,

19

RECEIVED OF

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.