## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED_4/12/38	_ IF SO HOW AND LOCATION FROM //// FIRST MANHOLE DOWN STREAM
House No. 338	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED 6	CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR
WAS ATTACHED TO MAIN	
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.    V   V   V   V   V   V   V   V   V
MUGIZ ATTER SEEZER CORERA NOVO ESEZ CO	The Windshadaan in aloca as of anow as of the same
SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE 3959 PERMIT TO TAP SEWER MASSILLON, OHIO WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE. Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.