

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3960

DATE INSPECTED 4/15/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

187'

HOUSE NO. 82

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

187

8' deep

SIZE OF PIPE USED 6


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

APR 15 '38

REMARKS:

Connected to lateral of next house. W.
house on West connected to wrong lateral when it was connected up,

NOT TO BE ANSWERED BY INSPECTOR
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
NO. 3960
PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/15 19
RECEIVED OF William Koehler FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary SEWER, ON THE South

OF North Ave N.E. AVE., TYPE OF STREET parade
ST.

THE PREMISES BEING LOT No. 12 (88) House No. 122-2nd St

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Her Early

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.

1/3
This Lateral
for tin shop
on North Ave
N.E.