

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

N^o. 3972

AND SIGNED WHEN RETURNED

DATE INSPECTED 6/18/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

308

HOUSE NO. 842

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

308 6' deep

WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR

Geo Earley
HOUSE

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SHEFFIELD AVE. N.E.

HOUSE

6' deep

76" deep

308

M.H.

SIGNED

John E. Egan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

EC. 81111

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 3972
PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/17 19

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE.,

TYPE OF STREET

ST.,

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.