

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3996

DATE INSPECTED 9/15/38

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

29'

HOUSE NO. 1919

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

29'

7'6" deep

SIZE OF PIPE USED 6" mfr

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

MAIN AVE. W.



SIGNED

John E. Thomas

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK H.M.P. 9-1-

REMARKS:

End of exis lateral was 3° N. of So. Curb Main Ave. W. ST.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 3996
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/14 1919
RECEIVED OF L. H. Smart FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED D. Daugherty
TO TAP Sanitary SEWER ON THE South
OF Irwin Ave. N. AVE., TYPE OF STREET dirt
ST.,
THE PREMISES BEING LOT No. 10323 House No. 1919

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. H. Smart

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.