

N^o 3998FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED11
18DATE INSPECTED 10/31/38IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. NEW HOUSE.DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHSIZE OF PIPE USED 6"

5'-6" deep

WAS LATERAL AT CURB? NO

NAME OF CONTRACTOR

WAS ATTACHED TO MAIN NO

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

19TH ST. N. W.
← N5'-6" deep
7'-6" deep
LOT LINE
CURB LINE
49'
IRON. P.I.
HOWARD

SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10/4/38

REMARKS:

NO. 3998

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO

10/3

19

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER. ON THE

OF

AVE., TYPE OF STREET

ST.,

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.