

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4009

DATE INSPECTED

11/15/38

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

204

HOUSE NO.

146

DISTANCE FROM FIRST MANHOLE
DOWN-STREAM-TO-DITCH-AT
CURB, LINE AND DEPTH

204 - 9d

WAS LATERAL AT CURB?

Yes

WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR


Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

TREMONT AVE. S.E.



see attached sketch



SIDE WALK

204'

SIGNED

Inspector for City

CURB LINE

FILED AT ENGINEER'S OFFICE

11/15/38

OK G.C.W.

REMARKS:

56' to first X

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4009

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/14 19

RECEIVED OF

W. W. Pille Estate

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

L. W. Smart

TO TAP

Sanitary

SEWER. ON THE

North

OF

Tremont Ave S.E.

AVE.,
ST.,

TYPE OF STREET

gravel

THE PREMISES BEING LOT No.

1147

House No.

146

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

L. W. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

San Juen to Creek

stack to roof

stack outside
Vent for San.

Bath Sew

PIPE

old line cut off at this point
cemented shot
New stack (move from back corner)
Plumber took up

Down Spout

Downspout

Downspout

Wise

6" VSP

Tremend

Wye

Tee

Downspout Wye?

Downspout Pile?

Vertical View