

N^o 4029

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

$\frac{3}{2}$

DATE INSPECTED 3/2/39

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

7-1

HOUSE NO. WHITTIER SCHOOL

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

79'

WAS LATERAL AT CURB? Yes


NAME OF CONTRACTOR

Sautzerhoser

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

ROTC H. AVE, N.E.



CURB LINE.

M.H. ⊙

79'

SIGNED

John E. Brown
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

3/2/39

REMARKS:

28' from curb line in start.

OK 3/2/39

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4029

PERMIT TO TAP SEWER

MASSILLON, OHIO,

19

RECEIVED OF

Longfellow Plumbing & Heating Co.

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Branch of Main Sewer

TO TAP

Sanitary

SEWER, ON THE

North

OF

Rt. 2 Ave. N. E.

AVE., TYPE OF STREET
St.,

Dist.

THE PREMISES BEING LOT No.

7434

HOUSE No.

11th St. S. E.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Longfellow

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.