

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4030

DATE INSPECTED 3/7/39

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

140'

HOUSE NO. 1446

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

140'

6'd

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Yes


NAME OF CONTRACTOR

Smart

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

NISH



N 1st NE

SIGNED

John E. Hiner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Measurements hit lateral right on the nose

M.H.

3/11/39

LAK E

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No. 4030

MASSILLON, OHIO,

3/7

19:

RECEIVED OF

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.