

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4066

DATE INSPECTED 10/11/39

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE No. YORK SCHOOL

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SCHOOL HOUSE.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10/11/39

REMARKS:

10/10

7/1/07

18

P. E. B. L. e

22

Board of Education - J. H. S.

11-11-11

ON THE 1st of May 1945

22nd Feb

dist

Pt 0.726

Y. A. L.

[illegible]

P. E. B. K. P.

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.