

NO. 4081

DATE INSPECTED 12/9/39

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 86'

HOUSE No. 306


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT _____ TO OBSERVE
CURB LINE AND DEPTH 86' - 5" 6

WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR Jimart

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. NAT OF



SIGNED John Chover

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 12/9/39

REMARKS: continued from the back of the page

12/9/39

NO. 4081

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/8

RECEIVED OF L. W. Smart

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Home Owners Loan

TO TAP Sanitary

SEWER, ON THE East

OF 11th St.

AVE., TYPE OF STREET dist

THE PREMISES BEING LOT No. 3132

HOUSE No. 306

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. W. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

8:30

Sanitary