


35

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 4086

DATE INSPECTED 1/6/40 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 190 ~ "
HOUSE NO. 432 DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
SIZE OF PIPE USED 6" CURB LINE AND DEPTH 190 - 2'6" d
WAS LATERAL AT CURB? Yes NAME OF CONTRACTOR Geo. Carley
WAS ATTACHED TO MAIN Yes
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



M.H. 0

SIGNED

John [Signature]
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

1/6/40

REMARKS:

NO. 4086

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1-2

19

RECEIVED OF

Dr. Seth Hattery

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

Geo. Early

TO TAP

San Sewer

SEWER, ON THE

Water

OF

Lake Ave. N.E.

AVE.,
ST.,

TYPE OF STREET

Dist

THE PREMISES BEING LOT No.

O.L. 159

HOUSE No.

432
~~15~~

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Geo. Early

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.