

N^o 4087

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1/13/40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

18' 7'6" d.

HOUSE No. 1021

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

21' 7'4"

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? NO

NAME OF CONTRACTOR


Geo Carley

WAS ATTACHED TO MAIN NO

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



OXFORD AVE. N E.



SIGNED

John Chinner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

1/15/40

REMARKS:

Old line was giving trouble so new line was put in

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4087
PERMIT TO TAP SEWER

MASSILLON, OHIO, Jan 12 19

RECEIVED OF David D. Doud FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Geo. Early

TO TAP Sanitary SEWER ON THE South

OF Oxford NE AVE., TYPE OF STREET Asphaltic Co
St.,

THE PREMISES BEING LOT No. 8409 House No. 1021

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Geo. Early

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.

old account
in ledger 2/11/40