

9/16

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4106

DATE INSPECTED 5/7/40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

132

HOUSE NO. 519

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

132 - 7'd


WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR

Smart

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John E. Thomas
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5/8/40

REMARKS:

10/16

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4106

PERMIT TO TAP SEWER

MASSILLON, OHIO,

19

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

*Adged 7/1/40 - 400
New account.*