

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4122

DATE INSPECTED 6/1/40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 426

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB?

NAME OF CONTRACTOR

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

ONE PIPE OFF MAIN FULL OFF ROOTS.
CAUSE OF RODING. BROKE A PIPE.



SIGNED

John E. Hanner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6/3/40

REMARKS:

2/9
Clean out Sewer line
Ledges - 800

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4122
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29 19
RECEIVED OF C. H. Anderson FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED His Land
TO TAP Sanitary SEWER ON THE East
OF 5th St AVE., TYPE OF STREET Mail
ST.,
THE PREMISES BEING LOT No. 1763 House No. 426

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR D. Phant Land

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.